Work Order ID 54815-

December 22, 2009 1:26:54 PM



Page 1

Item ID:

D3709-3

1/05/10

Accept

Setup Start

Stop

Stop



Revision ID:

Item Name: Angle

Required Date: 1/15/10

Start Qty: 6.00

Cust Item 1D: Customer:

Reference:

Start Date:

Approvals:

Process Plan:

CA

Req'd Qty: 6.00

Date: 09/12/23 Tooling:

Date:

Run Start

OC:

Date:

SPC (Y/N):

Date:

Sequence ID/ Work Center ID

Operation Description

Set Up/ Run Hours

Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Qty

图 10-1-7

Reject Number

Insp. Stamp

Draw Nbr

Revision Nbr

D3709

Rev A

100

FLOW CNC Waterjet

6061.063

Waterjet

FLOW WATER JET

Memo

necessary

QC2- Inspect parts off machine FAI/FAIB

0.00

0.00

1-Cut as per Dwg D3709 Dwg Rev: A

Prog Rev:

****grain direction on a 45 degree ****

2- Deburr if

110

120

0.00 0.00

B 10-1-1

Quality Control

QC8- Inspect parts - second check

Memo

0.00

Memo

Quality Control

Work Order ID 54815

December 22, 2009 1:26:55 PM

Page 2

Item ID: Revision ID:

D3709-3

Accept

Setup Start

Stop



Item Name: Start Date:

Angle

1/05/10 Required Date: 1/15/10

Start Qty: 6.00 Req'd Qty: 6.00

Cust Item ID: Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

Small Fab

Small Fab

Operation Description

Small Fab

Memo

Form as per dwg D3709

Set Up/ Run Hours 0.00

Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Memo

Memo

0.00

Sp 10/03/01

140

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00

8 (0/03/03

HandFinish land Finishing

Chemical Conversion Coat per QSI005 4.1

0.00

0.00

px 10-03-08

Work Order ID 54815

December 22, 2009 1:26:55 PM

Page 3

Item ID:

D3709-3

Accept

Setup Start

Stop

Revision ID:

Start Date:

Item Name: Angle

Required Date: 1/15/10

1/05/10

Start Qty: 6.00

Req'd Qty: 6.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

Quality Control

Operation Description

QC3-Inspect Part Finish

Memo

Set Up/ Run Hours

0.00

0.00

Draw Number

10/03/02

Draw Plan Rev. Code

Reject Accept Qty

Qty

Reject Insp. Number

Stamp

170

Packaging

Packaging

Identify as per dwg & Stock Location 85

Memo

0.00

0.00



Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

10/03/05 Aff MK 10-3-4

December 22, 2009 1:26:53 PM

Work Order ID: 54815

Parent Item: D3709-3

Parent Item Name: Angle

Comments:

Component Item ID/	Replacement	Mfg/
Item Name	Item ID	Purch
M6061T6S.063	9)	Purchase

6061-T6 .063 Sheet

Last

Location

Route

Seq ID

Primary

Item Location

No

Purchased

Start Date: 1/05/10

Required Date: 1/15/10

Start Qty: 6.00

Required Qty: 6.00

Remaining Qty Date Status Qty To Pick Issued Issued

1.6800

B 10-1-7

Warehouse Loc Qty Loc Code Location Main Warehouse MAT 55.73772105 110551 29.6341211 112939 26.1036

Unit of

sf

Measure

Qty on

55.7377

Hand

DART AEROSPACE LTD	Work Order:	54815
Description: ANGE	Part Number:	D3709-3
Inspection Dwg: D 3709-3 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
1,35	4 .030	1,353	×			
26.76		27.25	x	•		
.063	TL :010		*			
			-			
	H					
				-		
						(1

Measured by:	J.	Audited by:	Prototype Approval:	N/A
Date:	113	Date: da O	Date:	N/A

Rev	Date	Change	Revised by	Approved
LEA	Date	Ollange	V 1/ 11 A4	
A		New Issue	KJ/JLM	



